

SANBAG

San Bernardino Associated Governments Monthly Construction Report State Route 30/210

Construction through September 2001

Segment 1: View looking east at the Drainage System No. 4. Bridge in photo is the Benson Avenue Overcrossing.



Cucamonga Creek Channel: Ironworkers placing rebar for the final portion of the drainage structure.

Segment 2: Excavation activity between Mountain Avenue and San Antonio Avenue.



19th Street and Beryl Avenue: Demolition of street for construction of box culvert drainage system.



Deer Creek Channel: Placement of concrete for walls and deck of drainage structure.



Segment 4: Excavation and placement of pipe for Drainage System No. 8.